




- Key**
- Existing OHL
 - Proposed OHL Alignment
 - Proposed Tower Position
 - Temporary Diversion
 - Temporary Diversion Structure
 - Borrow Pit Search Area
 - Proposed Conductor Pulling Area (EPZ)
 - Proposed Retained Access Track
 - Proposed Access – Temporary
 - Existing Track (No Upgrades Required - Good Condition)
 - Existing Track (Upgrades Required - Fair Condition)
 - Existing Track (Upgrades Required - Poor Condition)
 - Existing Track (Upgrades Required - Very Poor Condition)
 - ▲ Existing Bellmouth - Minimal Work Required
 - ▲ Proposed Bellmouth Required - Temporary
 - ▲ Proposed Bellmouth Required - Permanent




Client: **Scottish & Southern Electricity Networks**
TRANSMISSION


Project: **Dunoon to Loch Long 132kV OHL Rebuild**

Title: **Figure 2 Site Layout Sheet 1 of 4**

Date: 20/01/2023 Scale: 15,000 @ A3
 Drawn: AS Checked: IM Approved: SM



- Key**
- Existing OHL
 - Proposed OHL Alignment
 - Proposed Tower Position
 - Temporary Diversion
 - Temporary Diversion Structure
 - Borrow Pit Search Area
 - Proposed Conductor Pulling Area (EPZ)
 - Proposed Retained Access Track
 - Proposed Access – Temporary
 - Existing Track (No Upgrades Required - Good Condition)
 - Existing Track (Upgrades Required - Fair Condition)
 - Existing Track (Upgrades Required - Poor Condition)
 - Existing Track (Upgrades Required - Very Poor Condition)
 - ▲ Existing Bellmouth - Minimal Work Required
 - ▲ Proposed Bellmouth Required - Temporary
 - ▲ Proposed Bellmouth Required - Permanent



Client:  **Scottish & Southern**
Electricity Networks
TRANSMISSION

Project: **Dunoon to Loch Long 132kV OHL Rebuild**


Title: **Figure 2
Site Layout
Sheet 2 of 4**

Date: 20/01/2023 Scale: 15,000 @ A3
Drawn: AS Checked: IM Approved: SM



Key


- Existing OHL
- Proposed OHL Alignment
- Proposed Tower Position
- Temporary Diversion
- Temporary Diversion Structure
- Borrow Pit Search Area
- Proposed Conductor Pulling Area (EPZ)
- Proposed Retained Access Track
- Proposed Access - Temporary
- Existing Track (No Upgrades Required - Good Condition)
- Existing Track (Upgrades Required - Fair Condition)
- Existing Track (Upgrades Required - Poor Condition)
- Existing Track (Upgrades Required - Very Poor Condition)
- ▲ Existing Bellmouth - Minimal Work Required
- ▲ Proposed Bellmouth Required - Temporary
- ▲ Proposed Bellmouth Required - Permanent

Client:  Scottish & Southern Electricity Networks
 TRANSMISSION

Project: Dunoon to Loch Long 132kV OHL Rebuild

Title: Figure 2 Site Layout Sheet 3 of 4

Date: 20/01/2023 Scale: 15,000 @ A3
 Drawn: AS Checked: IM Approved: SM



Key

- Existing OHL
- Proposed OHL Alignment
- Proposed Tower Position
- Temporary Diversion
- Temporary Diversion Structure
- Borrow Pit Search Area
- Proposed Conductor Pulling Area (EPZ)
- Proposed Retained Access Track
- Proposed Access – Temporary
- Existing Track (No Upgrades Required - Good Condition)
- Existing Track (Upgrades Required - Fair Condition)
- Existing Track (Upgrades Required - Poor Condition)
- Existing Track (Upgrades Required - Very Poor Condition)
- ▲ Existing Bellmouth - Minimal Work Required
- ▲ Proposed Bellmouth Required - Temporary
- ▲ Proposed Bellmouth Required - Permanent

Client:  **Scottish & Southern**
Electricity Networks
TRANSMISSION

Project: **Dunoon to Loch Long 132kV OHL Rebuild**

Title: **Figure 2
Site Layout
Sheet 4 of 4**

Date: 20/01/2023 Scale: 15,000 @ A3
 Drawn: AS Checked: IM Approved: SM