

Dunoon to Loch Long 132 kV OHL Rebuild Environmental Impact Assessment Report Volume 4 | Technical Appendix

Appendix 12.2 – Forest Landscape Design





TRANSMISSION

Scottish Hydro Electric Transmission plc Inveralmond House 200 Dunkeld Road Perth PH1 3AQ Tel: +44 (0)1738 456 000 www.ssen-transmission.co.uk

TRANSMISSION

CONTENTS

- Figure 12.2.1: Ballochyle Location and Context
- Figure 12.2.2: Ballochyle Current Tree Cover
- Figure 12.2.3: Proposed Felling under Current Arrangements
- Figure 12.2.4: Proposed Powerline Felling
- Figure 12.2.5: Indicative Powerline Restocking
- Figure 12.2.6: Photo Visualisation Viewpoint 1 Location
- Figure 12.2.7: Photo Visualisation Viewpoint 1 Current View
- Figure 12.2.8: Photo Visualisation Viewpoint 1 View of proposed Powerline Felling
- Figure 12.2.9: Photo Visualisation Viewpoint 1 View of Indicative Mature Restocking
- Figure 12.2.10: Photo Visualisation Viewpoint 2 Location
- Figure 12.2.11: Photo Visualisation Viewpoint 2 Current View
- Figure 12.2.12: Photo Visualisation Viewpoint 2 View of proposed Powerline Felling
- Figure 12.2.13: Photo Visualisation Viewpoint 2 View of Indicative Mature Restocking
- Figure 12.2.14: Glenfinart Location and Context
- Figure 12.2.15: Glenfinart Current Tree Cover
- Figure 12.2.16: Glenfinart Proposed Felling under Current Arrangements
- Figure 12.2.17: Glenfinart Proposed Powerline Felling
- Figure 12.2.18: Glenfinart Indicative Powerline Restocking
- Figure 12.2.19: Photo Visualisation Viewpoint 3 Viewpoint Location
- Figure 12.2.20: Photo Visualisation Viewpoint 3 Current View
- Figure 12.2.21: Photo Visualisation Viewpoint 3 View of Proposed Powerline Felling
- Figure 12.2.22: Photo Visualisation Viewpoint 3 View of Indicative Mature Restocking



