Creag Dhubh to Inveraray 275kV

Connection Environmental Impact

Assessment

Volume 4 | Appendix 7.3

Photos

June 2022



CONTENTS

INTRODUCTION	4
	1
INTRODUCTION	

1 INTRODUCTION

- 1.0.1 This appendix provides photographs showing the current condition of Kilmun Chapel and Burial Ground (1581) and Drimferm, Long Cairn (1582), together with the view south from Kilmun Chapel and Burial Ground (1581). The photos were taken during the field survey carried out as part of the cultural heritage assessment.
- 1.0.2 This appendix should be read in conjunction with Chapter 7: Cultural Heritage and Archaeology, EIAR Volume 2. The locations, and extents, of the heritage assets are shown on Figures 7.2a-b, Volume 3a.



Kilmun Chapel and Burial Ground (1581), taken from west



View south from Kilmun Chapel and Burial Ground (1581)



Drimfern, Long Cairn (1582), taken from north east