

VOLUME 4: APPENDIX V5-3.2: INDICATIVE TEMPORARY POLE SCHEDULE – ALTERNATIVE ALIGNMENT

VOLUME 4: APPENDIX V5-3.2: INDICATIVE TEMPORARY WOOD POLE SCHEDULE – ALTERNATIVE ALIGNMENT

Table 1: Temporary Underground Cable Diversion (see Volume 2: Figure V5-3.2: Proposed Dismantling Works and Temporary Diversions - Alternative Alignment)

Pole No.	Easting	Northing
89A	284731	962750
86A	284979	962897
50A	287625	962545
48A	287799	962457

Table 2: Temporary Wood Pole Diversion (see Volume 2: Figure V5-3.2: Proposed Dismantling Works and Temporary Diversions - Alternative Alignment)

Pole No.	Easting	Northing
95T	284265	962473
94T	284342	962526
93T	284418	962579
92T	284495	962632
91T	284571	962684
90T	284648	962737
89T	284724	962790
88T	284801	962843
87T	284885	962876
86T	284969	962909
85T	285053	962941
60T	287087	963241
59T	287142	963162
58T	287197	963083
57T	287252	963005
56T	287307	962926
55T	287362	962847
54T	287417	962769
53T	287472	962690
52T	287527	962611
51T	287582	962532
50T	287679	962483

Pole No.	Easting	Northing
49T	287778	962434
48T	287839	962366
47T	287900	962299
46T	287962	962229