



Key

- Existing Tower Position
- Proposed Retained Access Track
- Existing Track (No Upgrades Required - Good Condition)
- Existing Track (Upgrades Required - Fair Condition)
- Existing Track (Upgrades Required - Poor Condition)
- Existing Track (Upgrades Required - Very Poor Condition)
- Proposed All Terrain Vehicle
- Dunoon to Loch Long 132 kV Rebuild Tracks from s37 Application
- - Existing OHL Centreline
- Proposed Conductor Pulling Area (EPZ)
- - - Helicopter Operation Flight Route: Existing tower steelwork removal
- Indicative Helicopter Operation Compound
- - - Black Grouse Survey Area

Lekking Black Grouse Survey Records

- Black Grouse

Flight Activity Survey Records (Not In Flight)

- Black Grouse

Moorland Breeding Bird Survey Records

- Black Grouse

Winter Walkover Records

- Black Grouse

Labelled where number (flock size) is greater than 1.

0 1 2 3

 Kilometres

TRANSMISSION

Project: **Dunoon to Whistlefield (non s37) OHL Works**

Title: **Figure 6.13 Lekking Black Grouse Survey Results**

Date: 7/5/2023 Scale: 60,000 @ A3

Drawn: MAL Checked: IM Approved: SM