


Contains Ordnance Survey data © Crown copyright and database right 2023



Contains Ordnance Survey data $\textcircled{\mbox{\scriptsize C}}$ Crown copyright and database right 2023

	N ▲	Кеу
		Existing Tower Postion
	, (– – • Existing OHL Centreline
		 Helicopter Operation Flight Route: Existing tower steelwork removal
		Proposed Retained Access Track
		Existing Track (No Upgrades Required - Good Condition)
ər		Existing Track (Upgrades Required - Fair Condition)
		Existing Track (Upgrades Required - Poor Condition)
		Existing Track (Upgrades Required - Very Poor Condition)
		Proposed All Terrain Vehicle Route
		Dunoon to Loch Long 132 kV ——— Rebuild Tracks from s37 Application
		Indicative Helicopter Operation Compound
		Winter Walkover Survey Area
rmo	010	Winter Walkover Survey Results
	510	Mallard
		Red Grouse
		•
mor	е	
ne		0 500 4 000
Poi 2	0 -	Metres
		Scottish & Southern Electricity Networks
		TRANSMISSION
		Dunoon to Whistlefield (non s37) OHL Works
		Title Figure 6.14 Winter Walkover Survey Results Sheet 2 of 2
		Date: 7/5/2023 Scale: 10,000 @ A3
		Drawn: MAL Checked: IM Approved: SM