


81

82

83



Legend

Site Boundary


Survey Areas

Otter (200m)

Water Vole (100m)

Survey Results

- Otter - spraint
- Water vole - burrow not in current use
- GCN HSI - Below Average
- GCN HSI - Poor



Reproduced by permission of Ordnance Survey on behalf of HMSO.
Crown copyright and database right 2024 all rights reserved.
Ordnance Survey Licence number 0100022432.
SSEN Transmission take no responsibility for the release or accuracy of latest version Basemaps from Ordnance Survey


Project No: LT379

Project: Greens Substation EIA

Title:
Figure 9.2.2 Protected Species Results

Drawn by: NM Date: 6/11/2024

Drawing: LT000397_WSP_EIAR_V3_09_0922



Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community

381000m.E

82

83